

**A/C COMPRESSOR NOT OPERATIONAL / LOW
FREON—SHAFT SEAL LEAKS**

TSB 06-4-9

FORD:

2003 Escort
2003-2006 Focus, Mustang, Taurus
2003 Explorer Sport, Windstar
2003-2005 Excursion, Explorer Sport Trac
2003-2006 Escape, F-150, F-Super Duty,
Ranger
2004-2006 Freestar
2006 Low Cab Forward

LINCOLN:

2002 Blackwood
2006 Mark LT

MERCURY:

2003-2005 Sable
2004-2006 Monterey
2005-2006 Mariner

ISSUE

Some 2002-2006 vehicles equipped with an FS-10 A/C compressor may experience a non operational A/C compressor due to a low freon level caused by a leaking shaft seal.

ACTION

Replace the A/C compressor shaft seal following the Service Procedure.

SERVICE PROCEDURE

If the shaft seal on the front of the A/C compressor is leaking, replace the shaft seal (F1VY-19D665-A) and not the compressor assembly. Replacing the shaft seal should correct the leaking condition. When replacing the seal, follow the procedure outlined in Workshop Manual, Section 412-03.

PART NUMBER	PART NAME
F1VY-19D665-A	A/C Compressor Seal Kit

WARRANTY STATUS: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

OPERATION	DESCRIPTION	TIME
MT060409	Use Standard Labor Operation For Compressor Removal And Installation If Available, And Claim Additional Labor Required As Actual Time	Actual Time

DEALER CODING

BASIC PART NO.
19D665

CONDITION
CODE
42

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.